



200-200

Honda Accord 79 - 81, Honda Civic 78 - 83

Replaces
MC-5187



200-254

Honda

Replaces
E12-302, E12-303



200-260

Honda

Replaces
MC-8132, MC-8183, MC-8541, MNE301, MNE302, MNE303



300-5

Holden Commodore VN I V6 3.8L 88 - 90

DFI Module



300-6

Holden Commodore VN II, VG, VP, VR, VS, VT, VU, VX, VY V6 3.8L, Statesman VQ II, VR, VS, WH, WK V6 3.8L

DFI Module



300-350

Holden Commodore VL RB30E 3.0L 86 - 88
Holden Commodore VL RB30E Turbo 86 - 88
Nissan Skyline R31 RB30E 3.0L 86 - 88
Power Transistor



300-352

Holden Rodeo TF 4ZE1 2.6L 88 - 94

Power Transistor



300-354

Holden Barina SB C12NZ, C14NZ 1.2L, 1.4L 94 - 97



300-355

Holden Astra LB-LC, Honda Accord, Prelude, Subaru Brumby, Leone, Nissan Prairie M10, Pulsar N12

Replaces
E12-61



400-453

Ford Laser, Mazda 323, Nissan Patrol, Suzuki Swift

Replaces
J117



400-454

Ford Laser KF, KH, KH II, Mazda 323 BD, BG, Suzuki Swift

Replaces
J120, J170



400-455

Ford Courier PC, PD, PE, PS 2.6L, Laser KF, KH, Mazda 323 Astina BG B6 1.8L 89 - 94, B2600 2.6L G6 90 - 99

Replaces
J701



400-472

Mazda MPV JE EFI 3.0L V6 93 - 99

Replaces
J208



500-500

Daihatsu, Hyundai, Mitsubishi Pajero, Nimbus UA, UB, UC

Replaces
J152



500-501

Mitsubishi Scorpion GH, GJ, GK 2.6L 79 - 82
Mitsubishi Sigma GK, GE, GH, GJ 1.6L, 2.0L, 2.6L 77 - 84

Replaces
J104, J105



500-563

Daewoo Cielo, Holden Camira JD, JE, Nissan Pulsar N13



500-568

Hyundai Excel, Sonata, Mitsubishi L300 Express SF, SG, SH, Galant HG, HH, Lancer CA, Magna TN, TP, TR, TS

Replaces
J121



500-572

Mitsubishi Galant HJ 2.0L, Magna TH, TJ, 3.5L, Pajero NJ, NK, NL, NM 3.5L, Triton MJ, MK 3.0L, Verada KH, KJ 3.5L



600-1

Nissan Pintara R31 CA20E 86 - 90
Nissan Pintara Hatchback U12 CA20E 89 - 92

Replaces
J304



600-652

Ford Econovan, Laser KB, KC, KE, Meteor GB, GC, Telstar AR, Mazda 323 BF, 626 GB, GC, GD, 929 HB

Replaces
J106



900-955

Toyota

Replaces
131300-0011, 131300-0120



900-961

Toyota

Replaces
131300-511, 131300-0920, 13100-0601



1000-1

Ford, Holden, Mitsubishi, Nissan, Toyota

Replaces
BIM024



1000-6

Ford Falcon EA, EB, ED, EL 6 cyl. & V8

Replaces
BIM032



1000-8

Chev V8 HEI Distributors



1000-151

Ford Capri SC, SE 1.8L 92 - 93
Mazda 929 HC 3.0L 87 - 90

Replaces
J207



1100-1

Nissan 280ZX & Peugeot - 7 Pins

Replaces
0227100102, 0227100111, 0227100123



1100-2

Audi - 7 Pins

Replaces
0221600001, 006, 008, 0227100100, 101, 103, 104, 113, 116, 118, 137, 138, 139, 1227010001, 1227010100, 1227022008



1100-3

BMW, Citroen, Peugeot, Porsche - 7 Pins

Replaces
0227100200, 0227100204



1100-4

Citroen, Peugeot - 3 Pins

Replaces
0227100140, 1227022017, 018, 031, 1237010028, 029, 031, 038