



ND-1

Holden V8 253, 308
Electronic Ignition



ND-2

Ford Cleveland Early V8 302, 351
Gear Dia. **36.10mm** Oil Pump Shaft Dia. **13mm**
Electronic Ignition



ND-3

Ford Cleveland Late V8 302, 351
Gear Dia. **36.10mm** Oil Pump Shaft Dia. **12.5mm**
Electronic Ignition



ND-4

Holden Commodore V8 VN, VG, VP 5.0L
Oval Blue Plug

Replaces
9230065800



ND-5

Ford Falcon EA, EB 6cyl. Centre Fire Injection (CFI)

Replaces
9230065604, 9230065606



ND-6

Ford Falcon EA, EB, ED, EL 6cyl. Multi Point Injection (MPI)

Replaces
9230065603, 9230065605, F005D00002



ND-7

Holden Commodore V8 VP, VR, VS 5.0L
Square Black Plug

Replaces
9230065801



ND-8

HEI Chev V8 307, 350, 454 Small Block & Big Block

Note
Has Built-in 50,000 Volt Coil in the cap



ND-9

Chev V8 EFI



ND-12

HEI Ford V8 Cleveland Early 302, 351
Gear Dia. **36.10mm** Oil Pump Shaft Dia. **13mm**

Note
Has Built-in 50,000 Volt Coil in the cap



ND-13

HEI Ford V8 Windsor 260, 289, 302
Gear Dia. **31.5mm** Oil Pump Shaft Dia. **11.5mm**

Note
Has Built-in 50,000 Volt Coil in the cap



ND-15

HEI Ford V8 Windsor 351

Note
Has Built-in 50,000 Volt Coil in the cap



ND-16

Ford Windsor V8 260, 289, 302
Block Hole **38mm** Gear Dia. **31.5mm**
Oil Pump Shaft Dia. **11.5mm**
Electronic Ignition



ND-17

Ford Windsor V8 351
Block Hole **39.6mm** Gear Dia. **31.5mm**
Oil Pump Shaft Dia. **13mm**
Electronic Ignition



ND-18

Chev V8 307, 350, 454 Small Block & Big Block
Electronic Ignition



ND-19

Chev V8 Pro Billet CNC Machined Aluminium, Magnetic Pickup, High Performance

Additional part required
An Ignitor Box is required to operate this distributor - not supplied



ND-20

Holden Commodore V8 VT Series 1 & Holden Commodore VS Series 3 Ute

Replaces
F005D00000



ND-21

HEI Oldsmobile V8 350, 400, 425, 455

Note
Built-in 50,000 Volt Coil in the cap



ND-22

HEI Pontiac V8 267, 305, 350, 400, 455

Note
Built-in 50,000 Volt Coil in the cap



ND-24

Chrysler V8 273, 318, 340, 360 Electronic Ignition

Shaft Spec
Length from block hole to end shaft 100mm



ND-28

Chev V8 Pro Billet CNC Machined Aluminium, Magnetic Pickup, High Performance

Additional part required
An Ignitor Box is required to operate this distributor - not supplied



ND-29

Chrysler V8 426, 440
Will fit 383 but requires thicker washer at block hole

Shaft Spec
Length from block hole to end shaft 110mm



ND-31

Holden 253, 308 V8 Pro Billet CNC Aluminium

Additional part required
An Ignitor Box is required to operate this distributor - not supplied



ND-32

Ford Cleveland 351 / 460 Big Block Electronic Ignition



ND-33

Chrysler 426, 440 V8 Pro Billet CNC Aluminium

Additional part required
An Ignitor Box is required to operate this distributor - not supplied



ND-34

Ford V8 Windsor 289, 302 5.0L EFI Block Hole 38mm, Gear 31.5mm, Oil Pump Shaft 38.4mm L 11.5mm Dia.

Replaces
E4ZE-12131-AA



ND-35

Ford V8 Windsor 351 5.8L EFI Block Hole 39.6mm, Gear 31.5mm, Oil Pump Shaft 38.4mm L 13mm Dia.



ND-36

Jeep 4 cylinder EFI

Replaces
56041034



ND-37

Jeep Cherokee 4.0L 6 cylinder EFI 94 - 01

Replaces
56027028



ND-38

HEI High Performance Chev V8
All engines sizes, small & big blocks

Note
Has Built-in 65,000 Volt Coil in the cap



ND-39

Chev 6 cylinder EFI



ND-40

Ford 6 cylinder



ND-150

Ford Courier 4x2 / 4x4 G6 2.6L 91 - 96
Ford Raider 4x4 G6 2.6L 91 - 97

Replaces
T2T52971



ND-152

Ford Telstar AV F2 Turbo 2.2L 89 - 91

Replaces
T4T73472



ND-153

Ford Telstar AY FS 2.0L 94 - 96
Mazda 626 2.0L 94 - 96

Replaces
D4T93-01



ND-154

Kia Mentor SOHC 8V B5 1.5L 96 - 98
Ford Festiva WF B3/B5 1.3L/1.5L 98 - 00

Replaces
KK370-18-200



ND-155

Ford Festiva WB B3 1.3L 94 - 97
Ford Festiva WD B3 1.3L 97 - 98

Replaces
T2T57071



ND-250

Honda

Replaces
TD-30U



ND-251

Honda Prelude DOHC H23A1 2.3L 91 - 96
Honda Prelude VTI-R/VTEC H22A1 2.2L 94 - 96

Replaces
TD-61U



ND-252

Honda

Replaces
TD-01U



ND-253

Honda Concerto HW D16A6 1.6L 89 - 92

Replaces
TD-02U, TD-18U



ND-254

Honda Civic GLi D15B7 1.5 L 93 - 95

Replaces
TD-41U



ND-255

Honda Civic VTI D16Y1 1.6L 94 - 95

Replaces
TD-42U, TD-48U



ND-256

Honda CRX VTEC DOHC B16A2 1.6L 92 - 98

Replaces
TD-44U, TD-68U



ND-258

Honda Civic City / CRX 95 -

Replaces
D4T94-04



ND-259

Honda Integra 1.6L D16A3 86 - 89

Replaces
TD-22U, TD-28U



ND-260

Honda Accord CB7 EXi F22A5 2.2L 89 - 93, Accord F22A6 2.2L 92 - 94, Accord CD5 EXi F22B3 2.2L 93 - 97

Replaces
TD-31U, TD-34U, TD-58U



ND-261

Honda Prelude S.O.H.C. F22A1 2.2L 91 - 96

Replaces
TD-52U, TD-59U



ND-263

Honda Civic Carburettor Engine

Replaces
D4W86-02, D4W86-11, D4W88-01, D4W88-06, D4W88-07



ND-264

Honda Civic EG Breeze D13B2 1.3L 91 - 93
Honda Civic EG Breeze D15B4 1.5L 91 - 93

Replaces
D4W86-12, D4W86-13, D4W90-03, D4W90-07



ND-265

Honda Integra GSi / GLi 1.8L 93 - 01

Replaces
TD-46U, TD-55U



ND-266

Honda CRX ED, EE, DOHC D16A8 1.6L 88 - 92

Replaces
TD-03U



ND-267

Honda Integra DOHC B18A1 1.8L 89 - 93

Replaces
TD-23U, TD-24U



ND-268

Honda CR-V 4x4 B20B3 2.0L 97 - 01

Replaces
TD-97U



ND-269

Honda Civic DOHC D16A8 1.6 L 91-93

Replaces
TD-43U



ND-270

Honda Legend V6 Auto C27A1 2.7L 88 - 91

Replaces
TD-01T



ND-271

Honda Prelude DOHC B 20A6 2.0L 87 - 91
Four Wheel Steer

Replaces
TD-02P



ND-272

Honda Accord VTi F22B1 2.2L 93 - 97

Replaces
D4T92-04



ND-273

Honda Odyssey SOHC F22B6 2.2L 96 - 97

Replaces
D4T93-03



ND-274

Honda Accord VTi F23A7 2.3L 97 - 00
Honda Odyssey VTEC SOHC F23A7 2.3L 98 - 01

Replaces
D4T96-08



ND-275

Honda Civic Del Sol 1.6L VTEC 96 - 97

Replaces
TD-81U



ND-277

Honda Prelude A 20A2 2.0L 86 - 87 Unleaded

Replaces
TD-01N



ND-350

Holden Commodore VL RB30E 3.0L 86 - 88
Holden Commodore VL RB30E Turbo 3.0L 86 - 88

Replaces
22100-42L00



ND-352

Holden Rodeo TF 4ZE1 2.6L 88 - 92

Replaces
D4P87-01



ND-354

Holden SB Barina C12NZ, C14NZ, C14SE 94 - 01
Holden Combo Van C14NZ, C14SE 96 - 01

Replaces
0237521024



ND-401

Ford Econovan Maxi 2000 FE 2.0L 86 - 00
Mazda E2000 FE 2.0L 86 - 89 **Note** Points Distributor

Replaces
T3T07872



ND-452

Ford Festiva

Replaces
T2T50171



ND-453

Ford Capri SA B6 1.6L 89-90, Laser KC/KE B6 1.6L 85-90
Meteor GC B6 1.6L 85-87, Mazda 323 BF B6 1.6L 87-89

Replaces
T4T1973, T4T72071, T4T73780



ND-454

Ford Laser KF/KH B6 1.6L 90 - 94, Mazda 323 BG B6 1.6L 89 - 94, 323 Protege BA B6 1.6L 94 - 96

Replaces
T2T82272, T2T82277, T2T82280



ND-455

Ford Laser KF/KH BP SOHC 1.8L 90 - 94
Mazda 323 BG/BA B6/BP SOHC 1.8L 89 - 98

Replaces
T2T53171



ND-456

Ford Laser KJ / KJII (KL) B6D 1.6L/1.8L 94 - 96
Mazda 323 BA B6D/BPD DOHC 1.6L/1.8L 98 - 00

Replaces
T2T57371



ND-457

Ford Laser KJIII B6D/BPD 1.6L/1.8L 96 - 99
Mazda 323 B6D/BPD 1.6L/1.8L 96 - 99

Replaces
T2T60371



ND-459

Ford Telstar / Mazda

Replaces
T6T57871



ND-460

Ford Telstar AX FS 2.0L 92 - 94
Mazda 626 GE/GF FS/FSD 2.0L 92 - 02

Replaces
D4T90-02



ND-461

Ford Telstar / Mazda

Replaces
T2T57971



ND-462

Ford Telstar/Probe KL01 V6 2.5L 92 - 97, Mazda 626/ MX6 KL01 V6 2.5L 91 - 97, Eunos V6 2.0L/2.5L 89 - 98

Replaces
T0T57071



ND-463

Eunos / Ford Telstar / Mazda V6 KF34
Note has 1 pick up sensor - crank angle sensor J838

Replaces
T0T57271



ND-464

Mazda 121 DB B3 1.3L 90 - 97
Mazda 121 DW B5 1.5L 94 - 96

Replaces
D4T89-02



ND-465

Ford Laser KF/KH BP DOHC 1.8L 90 - 94
Mazda 323 Astina BG B6 DOHC 1.8L 89 - 94

Replaces
T2T52471



ND-466

Mazda 121 Metro B3 1.3L 96 - 00
Mazda 121 Metro B5 1.5L 96 - 00

Replaces
T2T60572



ND-468

Ford Telstar AT F2 Turbo 2.2L 87 - 89
Mazda 626/MX6 GD F2 Turbo 2.2L 87 - 91

Replaces
T4T73471



ND-469

Mazda MX-5 DOHC BPD 1.8L 93 - 00

Replaces
T1T48371



ND-471

Ford Courier 4x4 AM 2.6L 87 - 90
Mazda B2600 4x4 4G54 2.6L 87 - 90

Replaces
T3T63972



ND-473

Eunos / Ford Telstar / Mazda V6 KF34
Note has 2 pickup sensors - crank angle sensor J848

Replaces
T0T57171



ND-475

Ford Courier G6 2.6L 96 - 99
Mazda B2600 UF G6 2.6L 96 - 99

Replaces
T2T57972A



ND-476

Eunos V6 KF-01 Import Model
Note runs external coil

Replaces
T0T52071



ND-500

Mitsubishi L200, L300 1.6L 4G32 Saturn Engine 80 - 85
Points Ignition

Replaces
T3T05778



ND-550

Mitsubishi Express, Starwagon SF, SG, SH 2.4L 4G64 EFI

Replaces
T3T64171



ND-552

Mitsubishi Nimbus UF 16V 4G64 2.4L 93 - 98

Replaces
T6T58071



ND-553

Mitsubishi Magna TE/TF 6G72 V6 3.0L 96-99 TH/TJ 6G74 V6 3.5L 99-05, Verada KE/KF/KH 6G74 V6 3.5L 96 - 00

Replaces
T0T57671



ND-554

Mitsubishi Magna TE 4G64 2.4L 96 - 97
Mitsubishi Magna TF 4G64 2.4L 97 - 99

Replaces
T2T60071



ND-555

Mitsubishi Lancer CE 4G15S3 1.5L 96 - 04
Mitsubishi Mirage CE 4G15 1.5L 96 - 01

Replaces
T2T59571



ND-556

Mitsubishi Lancer CC 4G92/4G93 1.6L/1.8L 92 - 96
Proton Persona Xli/Satria/Wira 4G92 1.6L 95 - 01

Replaces
T6T57671A



ND-557

Mitsubishi Lancer CB 4G15 Carby 1.5L 90 - 92
Mitsubishi Lancer CC 4G15 Carby 1.5L 92 - 96

Replaces
T6T87372



ND-558

Mitsubishi Magna TN, TP, TR, TS 2.6L EFI 87 - 96

Replaces
9230065401



ND-559

Mitsubishi L300 4G63 2.0L 86 - 90
Electronic Ignition - used to replace points distributors

Replaces
MD115846



ND-561

Mitsubishi L300 Express SJ / WA 4G64 EFI 2.4L 94 - 01

Replaces
T2T56071



ND-563

Daewoo Cielo 1.5L SOHC G15MF 94 - 98

Replaces
1103678



ND-564

Mitsubishi Lancer CB 4G15 SOHC 1.5L 90 - 92
Proton Persona GLi/Satria/Wira 4G15 1.5L 95 - 01

Replaces
T6T57171A



ND-565

Mitsubishi Galant HG 4G63 DOHC 2.0L 89 - 90

Replaces
T1T49071



ND-566

Hyundai Lantra KF G4CR 1.6L 91-92 MitGalantHH 4G63
DOHC 2.0L 90 - 92 Lancer CB 4G61 DOHC 1.6L 90 - 92

Replaces
T1T49571



ND-567

Mitsubishi Galant HH 4G63 SOHC 2.0L 90 - 92
Mitsubishi Nimbus UF 8V 4G64 2.4L 92 - 93

Replaces
T2T53372



ND-568

Mitsubishi Lancer CA 4G15 Carby 1.5L 88 - 90
Mitsubishi Lancer CA 4G15 EFI 1.5L 89 - 90

Replaces
T3T64173



ND-569

Mitsubishi Pajero V6 EFI 6G72 3.0L
Mitsubishi Diamante 3.0 92 - 95

Replaces
T5T42771



ND-570

Mitsubishi Galant HJ 4G63 SOHC 2.0L 93 - 94

Replaces
T6T58271



ND-571

Mitsubishi Lancer CE 4G93 EFI 1.8L 96 - 01

Replaces
T2T58272



ND-572

Mitsubishi Pajero NH V6 EFI 6G72 3.0L 91 - 93

Replaces
T5T42371



ND-573

Mitsubishi Nimbus UG 16V 4G64 2.4L 99 - 02

Replaces
T2T60271



ND-575

Daewoo Matiz F8CV SOHC 796cc 3cyl. 99 - 01

Replaces
96239411



ND-576

Hyundai Excel
Note has crank angle sensor J913

Replaces
27100-24750



ND-577

Hyundai Excel & S Coupe
Note has crank angle sensor J914

Replaces
27100-24511



ND-600

Nissan Z20, Z22, Z24 Engine
Points Ignition

Replaces
22100-20G15, 22100-23G15



ND-602

Datsun / Nissan H20 Engine
Points Ignition

Replaces
22100-20G15, 22100-23G15



ND-611

Datsun / Nissan L16, L18, L20 4cyl. Engine
Points Ignition



ND-612

Datsun / Nissan L24, L26, L28 6cyl. Engine
Points Ignition

ND-615

Datsun / Nissan J15, J16 4cyl. Engine
Points Ignition



ND-650

Nissan Bluebird U13 KA24DE 2.4L 93 - 97

Replaces
22100-1E400, D4P90-02



ND-652

Datsun / Nissan A10, A12, A14, A15 4cyl. Engines
Electronic Ignition - used to replace points distributors

ND-654

Nissan Pulsar N15 GA16DE 1.6L 95 - 00

Replaces
22100-OM300, D4T92-01



ND-655

Nissan Pulsar N14 GA16DE 1.6L 93 - 95

Replaces
22100-78A00, 22100-78A10, D4P86-05





ND-658

Nissan Patrol GQ TB42E 4.2L EFI 91 - 97

Replaces
22100-37J10, T0T42171



ND-659

Nissan NX AB13 SR20DE 2.0L 91 - 96
Nissan Pulsar N14/N15 SR20DE 2.0L 91 - 00

Replaces
22100-53J02, D4P88-03



ND-660

Nissan Skyline R31 RB30E 3.0L 86 - 90
Nissan Skyline R31 GTS RB30E 3.0L 88 - 89

Replaces
22100-42L10, 22100-42L11, 22100-42L12



ND-661

Nissan Micra SLX CG13DE 1.3L 95 - 97

Replaces
22100-99B01, 22100-99B02, 22100-99B03, 22100-99B04



ND-662

Nissan Maxima J30 VG30E V6 3.0L 90 - 95

Replaces
D6P87-02



ND-663

Nissan Navara D22 KA24E 2.4L 96 - 97

Replaces
22100-15702, D4P87-03



ND-664

Nissan Navara D21 KA24E 2.4L 92 - 97
Nissan Navara D22 KA24E 2.4L 97 - 00

Replaces
22100-40F00, D4P87-03



ND-667

Nissan Navara D21 VG30E V6 3.0L 92 - 97
Nissan Pathfinder D21 VG30E V6 3.0L 92 - 95

Replaces
22100-88G00, 22100-88G01, D6P88-03



ND-668

Nissan Pathfinder R50 VG33E V6 3.3L 95 - 04

Replaces
22100-0W001, D6T94-02



ND-669

Nissan Navara D22 KA24E 2.4L 01 - 03

Replaces
T2T62071



ND-671

Nissan Z20, Z22, Z24 4cyl. Engines
Electronic Ignition - used to replace points distributors



ND-672

Nissan Skyline R33 SR20DET 2.0L 91 - 98
Nissan 200SX SR20DET 2.0L 91 - 98

Replaces
23731-50F01, 23731-50F02



ND-673

Nissan Navara D22 VG30E 3.0L V6 98 - 01, Navara D22 VG33E 3.3L V6 03 - 06, Pathfinder VG33E 3.3L V6 01 - 05

Replaces
22100-1W601, D6T96-02



ND-674

Nissan Terrano KA24E 2.4L 12 Valve OHC 97 - 00

Replaces
22100-1S802, D4T94-02



ND-675

Nissan Patrol GQ Y60 RB30S 3.0L 6cyl. Carby 90 - 97

Replaces
22100-62518



ND-750

Holden Barina MH G13B 1.3L 91 - 92
Suzuki Swift / Cino SF143 G13B 1.3L 89 - 95

Replaces
T2T72571, 33100-63B60



ND-752

Suzuki Swift / Cino SF413 GTi G13B DOHC 1.3L 89 - 90

Replaces
33100-64B10



ND-753

Suzuki Swift SF416 GLX G16B 1.6L 89 - 95

Replaces
33100-71C30



ND-754

Suzuki Vitara 4x4 Grand H20A V6 2.0L 95 - 99

Replaces
T1T48671



ND-755

Suzuki X-90 4x4 Targa G16B 1.6L 96 - 98

Replaces
T2T59071



ND-756

Suzuki Vitara EFI G16B 1.6L 91 - 00

Replaces
33100-58B10



ND-850

Subaru Brumby 1800 EA82 EFI Non Turbo 1.8L 88 - 90
Subaru Leone 1800 EA82 EFI Non Turbo 1.8L 88 - 90

Replaces
22100-AA450, D4P86-01



ND-905

Toyota Hi-Ace RH11, RH16, RH20 12R 1.6L 71 - 85
Toyota Hi-Lux RN13, 16, 20, 25, 30, 40 12R 1.6L 71 - 83
Toyota 12R Engines
Points Ignition



ND-907

Toyota Celica 18R-C 76 - 81, Corona 18R-C 74 - 81
Hi-Ace 18R 77 - 83, Hi-Lux 18R 77 - 83
Toyota 18R Engines
Points Ignition



ND-908

Toyota Dyna/Stout RU 5R 2.0L 67 - 85
Toyota Toyo-Ace RY16, RY31 5R 2.0L 74 - 85
Toyota 5R Engines
Points Ignition



ND-912

Toyota 4 Runner 84 - 87, Dyna 85 - 98,
Hi-Ace 83-89, Hi-Lux 84 - 86
Toyota 1Y, 2Y, 3Y, 4Y Engines Carburetted
Points Ignition



ND-926

Toyota Landcruiser 2F 4.2L 75 - 84
Toyota Landcruiser 3F 4.0L 84 - 92
Toyota 2F, 3F Engines
Points Ignition



ND-951

Toyota Starlet EP91 4E-FE 1.3L 96 - 99

Replaces
19020-11380



ND-953

Toyota Corolla AE92 4A-F 1.6L Carby 91 - 94

Replaces
19020-16200, 19020-16210



ND-954

Holden Nova LF, LG 7AFE 1.8L 93-96, Toyota Corolla
AE92, AE93, AE101, AE102, AE112 4A-FE, 7A-FE 92 - 01

Replaces
19020-16250, 19020-16260



ND-955

Toyota 1Y, 2Y, 3Y & 4Y 4cyl. Engines Carburetted Electronic Ignition - used to replace points distributors

Replaces
19030-71010, 19030-72020, 19030-72050, 19030-73040



ND-956

Toyota Camry SV21 3S-FE 2.0L 87 - 93
Toyota Celica ST162 3S-FE 2.0L 86 - 93

Replaces
19040-74020, 19040-74030, 19040-74031, 19040-74040



ND-957

Toyota Celica 5S-FE 2.2L DOHC 89 - 94
Toyota Camry SDV10R 5S-FE 2.2L DOHC 92 - 97

Replaces
19050-74040, 19050-74050



ND-959

Toyota Camry VZV21 2VZ-FE V6 2.5L 88 - 93

Replaces
19100-62020, 19100-62030



ND-960

Totoya Landcruiser FJ80 3F-E 4.0L 90 - 92

Replaces
19100-61240



ND-961

Toyota Hi-Ace 2RZ RZH 103, 113, 125 2.4L 89 - 01 Carby

Replaces
19020-75040



ND-962

Toyota Camry VDV10 3VZ-FE V6 3.0L 93 - 97
Toyota Vienta VCV10 3VZ-FE V6 3.0L 95 - 97

Replaces
19100-62050



ND-963

Toyota 4 Runner VZN130 3VZ-E V6 3.0L 90 - 96

Replaces
19100-65010



ND-964

Toyota Tarago TCR10 TCR11 TCR20 TCR 21
2TZ-FE 2.4L 90 - 93

Replaces
19100-76010



ND-966

Toyota Hi-Lux 2.7L 92-95

Replaces
19050-75020



ND-967

Toyota Cressida MX83 7M-GE 3.0L 88 - 93

Replaces
19100-42050



ND-968

Toyota Celica ST185R GT4 3S-GTE 2.0L 90 - 92
Toyota MR2 SW20 3S-GE 2.0L 90 - 95

Replaces
19100-88363



ND-969

Daihatsu Feroza 4x4 HD-E 1.6L 89 - 98

Replaces
19060-87104



ND-970

Toyota Celica ST204 5S-FE 2.2L 94 - 99
Note runs external coil

Replaces
19100-74050, 19100-74060



ND-971

Toyota Paseo EL44 5E-FE 1.5L 91 - 99

Replaces
19050-11010



ND-972

Toyota Corolla AE92 4A-GE 1.6L 89 - 91
Toyota Corolla AE93 4A-GE 1.6L 91 - 92

Replaces
19100-16250



ND-973

Toyota Landcruiser FZJ80 1FZ-FE 4.5L Twin Cam 92 - 98

Replaces
19100-66020



ND-974

Toyota Celica ST162SX 3S-GE DOHC 16V 2.0L 85 - 90

Replaces
19100-88362



ND-975

Daihatsu Applause A101 HD-E 1.6L 89 - 99

Replaces
19060-87111



ND-976

Toyota Landcruisers 2F & 3F Engines
Electronic Ignition - used to replace points distributors

ND-977

Toyota Hi-Ace RZH103/113, RCH12/22 2RZ-E 2.4L EFI
95 - 03, Toyota Hi-Lux RZN147R 1RZ-E 2.0L EFI 97 - 00

Replaces
19020-75031



ND-978

Daihatsu



ND-979

Daihatsu Charade G102 HC-E 1.3L 89 - 93

Replaces
19060-87106

ND-1150

VW Golf GTi 2H 1.8L 90 - 93

Replaces
0237520024



ND-1152

Seat Ibiza GTI 2E 2.0L 95 - 99, Seat Toledo GLX 2E 2.0L
95 - 99, VW Transporter T4 92 - 04

Replaces
0237520048



ND-1153

VW Golf II 19E 1G1 83 - 92

Replaces
0231170305

ND-1154

VW Polo 1.6L 90 - 94

Replaces
0237521050



ND-1155

VW Golf GTi 1.8L 16 Valve 86 - 89

Replaces
0237521010



ND-1156

VW Golf 3 1.8L 91-93

Replaces
0237520036

ND-1157

Seat Cordoba, Seat Ibiza, VW Golf 1.4L 95 - 99,
VW Kombi II

Replaces
0237521061

