



303-1

Air Flow Insert
Holden Rodeo TF 6VD1 V6 97 - 02
3 Pin Plug



303-2

Air Flow Insert
Holden Rodeo RA 6VE1 V6 3.5L 03 - 06
6 Pin Plug



303-3

Holden Rodeo TF 4ZE1 2.6L 93 - 98
3 Pin Plug



303-4

Holden Rodeo RA Diesel 4JH1 3.0L 99 - 06
5 Pin Plug



303-6

Holden Commodore VS - VY V6 3.8L & S/Charge 95 - 04
Holden Commodore VS - VY V8 5.0L 95 - 04
3 Pin Plug



303-9

Holden Frontera UT X20SE 2.0L 95 - 99

Replaces
0280217003



303-10

Holden Calibra YE C20XE 2.0L 93 - 97



303-12

Holden Astra TS X18XE, Z18XE 1.8L 98 - 06
Holden Astra AH Z18XE 1.8L 04 up
Holden Combo XC Z18XE 1.8L 02 - 06 4 Pin Plug



303-14

Holden Vectra JR - JS X25XE 2.5L 97 - 00
SAAB 900 II V6 2.5L 96 - 98



303-15

Holden Astra TR C18SEL, X20XE 1.8L, 2.0L 96 - 98
Holden Calibra YE X20XE 91 - 97
Holden Vectra JR, JS C20SEL, C22SEL 97 - 00



303-20

Holden Commodore, Statesman VZ L76 6.0L V8 06 - 07
Holden Commodore, Statesman VE 6.0L V8 07 - 08



403-3

Ford Courier PE, PG G6 2.6L 98 - 07, Econovan
F8-E, FE 1.8L, 2.0L 02 - 07, Laser KN, KQ 1.8L 98 - 03
Mazda 323 BJ 1.8L 98 - 03, Mazda B2600 UN G6 2.6L 98
- 07, MX5 NB BPD 1.8L 98 - 00, 3 Pin Plug



403-5

Ford Courier Raider PC, PD 2.6L G6 89 - 92
Mazda Bravo B2600 UF 2.6L G6 89 - 98
5 Pin Plug



403-6

Ford Courier Raider PC, PD 2.6L G6 89 - 92
Mazda Bravo B2600 UF 2.6L G6 89 - 98
6 Pin Plug



403-7

Air Flow Insert Ford Escape ZA, ZB, ZC 2.3L 04-
Laser KN, KQ 1.6L 98 - 03, Mazda 3 BK 2.0L, 2.3L 03-
323 BJ 1.6L 98 - 00, 6 GG, GY 2.0L, 2.3L 02-, B2500 2.5L
96-, MPV 2.3L 02-, MX5 NC 1.8L 05-, RX8 1.3L, Tribute



503-1

Hyundai Excel X3 G4EK, G4FK 1.5L 94 - 96
Hyundai S Coupe G4EK 1.5L 92 - 95



503-2

Hyundai Santa-Fe G4JS 2.4L 00 - 01
Hyundai Sonata G4JS 2.4L 01 - 02
KIA Optima G4KC 2.4L 01 - 02



503-3

Mitsubishi Magna TR-TJ 4cyl & 6cyl, Nimbus UF 2.4L,
Pajero NH-NL, Starwagon WA 4cyl & 6cyl,
Triton MH, MJ, MK 4cyl & 6cyl, Verada KR-KH
7 Pin Plug



503-4

Mitsubishi Challenger PA 6G73 97 - 01, Magna TJ-TW
Nimbus UG 4G64 2.4L 98 - 03, Outlander ZE 4G69 2.4L
02 - 04, Pajero NM, NP 6G74 3.5L 00 - 06, Triton MK
6G72 3.0L 03 - 06, Verada KJ, KL, KW 3.5L 00 - 05



503-5

KIA Carens T8-D 1.8L 99 - 02
KIA Shuma FB T8-D 1.8L 00 - 01
Spectra FB T8-D 1.8L 01 - 04
Sportage FE-D 2.0L 98 - 03



603-1

Air Flow Insert Nissan Maxima A33 VQ30DE 3.0L 99 up,
Patrol Diesel ZD30DDTI 3.0L Turbo 00 - 04, Pulsar N16
QG16DE, QG18DE 1.6L, 1.8L 00 - 04, Subaru Forester
S10 EJ205 2.0L Turbo 98 - 00, Impreza WRX



603-2

Air Flow Insert
Nissan X-Trail T30 QR25DE 2.5L 01 - 03
5 Pin Plug



903-1

Air Flow Insert Toyota
4 Runner, Avalon, Avensis, Camry, Celica,
Corolla, Echo, Hilux, MR2, Rav 4, Tarago, Yaris
5 Pin Plug



903-2

Air Flow Insert Toyota 4 Runner VZN 5VZ-FE 3.4L 98
- 02, Camry ACV36 2AZ-FE 2.4L 02 - 06, Kluger MCU
3MZ-FE 3.3L 03 up, Prado VZJ 5VZ-FE 3.4L 99 up,
Prius NHW11 1NZ-FXE 1.5L 00 - 03, 5 Pin Plug



1003-29

Ford Mondeo HA, HB, HC 2.0L 93 - 98
Ford Transit 2.0L 95 - 00



1003-30

Ford Explorer 4.0L 99 - 03
Ford Fairlane, Falcon, LTD AU 5.0L V8 98 - 02



1003-34

Ford Fairlane NC, NF, NL 5.0L V8 91 - 98
Ford Falcon EB, ED, EF, EL 5.0L V8 91 - 98
Ford LTD DC, DF, DL 5.0L V8 91 - 98



1103-3

Mercedes Benz

Replaces
0280217100



1103-4

Mercedes Benz

Replaces
0280217114, 0280217115



1103-5

Audi, Seat, VW

Replaces
0280217117



1103-6

BMW

Replaces
0280217124



1103-7

Mercedes Benz

Replaces
0280217500



1103-8

Volvo

Replaces
0280217511



1103-9

Mercedes Benz CLK 6cyl

Replaces
0280217515, 0280217516



1103-10

Mercedes Benz, Ssangyong Musso

Replaces
0280217517, 0280217518



1103-11

Audi, Seat, VW

Replaces
0280217529



1103-12

Mercedes Benz

Replaces
0280217810



1103-13

Audi, VW

Replaces
0280218002, 0280218003



1103-14

VW

Replaces
0280218013



1103-15

VW, Audi, Seat

Replaces
0280218017, 0280218018, 0986280208



1103-16

Alfa, Fiat

Replaces
0280218019



1103-17

Audi, VW

Replaces
0280218023



1103-18

Audi, VW

Replaces
0280218032, 0280218033, 0986280210



1103-19

Audi

Replaces
0280218034, 0280218035, 0986280211



1103-20

Audi, VW

Replaces
0280218063